


Work Process



01 Arranging works

To jog the materials on the lift using a guide plate before a guide plate descends



02 To Convey to the loading table

On arrival of the guide plate descends to put materials in the chucking device using an air gun for inflation



03 To Convey to the air table

On arrival of materials at loading table the chucking device will chuck the materials to automatically convey to the air table



04 To Convey to the cutting table

Materials conveyed by the chucking device will be on the slide air table to be automatically supplied to the front of the cutting table.



05 To return the feeding device

On completion of feeding, the slide air table shall return to the first place to prepare for next supply.

Features

- No scattering of materials from feeding, distribution, and loading provides best condition for double-sided printing.
- Labor cost savings thanks to minimal labors.
- Optimum efficiency system applying most suitably designed process movements
- No need for handling heavy materials may keep laborers away from musculo-skeletal disease
- Will produce satisfactory results for short-term orders and quality maintenance